

## **UHD50X and UHD30 Release Notes**

**06/19/2020**

### **Fixes**

1. Split Screen Issues
2. EDID - Unable to select 120Hz or 240Hz in some configurations. Must successfully program Auto EDID for this to be effective.

### **Requirements**

1. Requires USB-A to USB Cable and USB Flash Drive.
2. Windows PC is required for DDP update.

### **Update Methodology**

1. Update DDP Firmware.
2. Update System Firmware.
3. Auto EDID (must come AFTER 1 and 2.